

PROJECT PHOTOS



Installation of Waterproofing and Backfill and  
Compaction at Elevator Pit



First Courses of CMU being laid at Stairway 12



Scaffold Erection and Ongoing CMU at Stairway 12



Lintel installed at Doorway at Stairway 12



Concrete placed for footings at Auxiliary Building



Footings at Auxiliary Building stripped

PROJECT PHOTOS



Forming of Foundation Walls at Auxiliary Building



Forming of Foundation for Masonry Mockup



Installation of Metal Frame and Dens-Glass at Masonry Mockup



Installation of Sallyport Door Frame



Bracing of Sallyport Door Frame



Inside view of CMU work in Dispatch Area

PROJECT PHOTOS



Overview of CMU work at Stairway 11 and Elevator



Stairway 11 and Elevator completed; Scaffolding being disassembled



Stairway 11 and Elevator completed



Stairway 12 completed



Elevator Shaft Completed



Sallyport Door Frame Installation Completed